

VEHICLE INSPECTION REPORT

BX59DFJ

Daf LF 45.160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 24/12/2009

Year 2009

Mileage 182,929 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRAE45FF0L354152

Body Style Box Van

Service history Yes

MOT Due 30/11/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

Rear Doors Roller

SEATING AREA, SINK

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1




OSO2

OSO3


OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint

2: Bumper Front
Rusted
Over 5mm



3: Bumper Front
Dented
Between 10mm + 30mm

4: Grille Front
Broken
Replace



5: Door nsf
Scratched
Over 25mm Not Thru Paint

6: B Post ns
Scratched
Over 25mm Not Thru Paint



7: Other
N/A
N/A

8: Qtr Panel osr
Cracked
Replace



9: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

10: Other
N/A
N/A



11: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

12: Other
N/A
N/A

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK