

VEHICLE INSPECTION REPORT

C430676

DONBUR CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2016	Colour	BLUE	Brakes	Drum
Year	2016	VIN	SEPPM39DUGL065495	Axle Combi	Tri
Mileage	Not Showing	Body Style	Trailer	Rear Suspension	Air
Fuel Type		MOT Due	30/06/2026	Rear Doors	Barn

BWP AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



