

VEHICLE INSPECTION REPORT

C291770

Iveco Stralis 460

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 07/07/2014

Year 2014

Mileage 270,310 Km Not Warranted

Fuel Type

Colour WHITE

VIN

Body Style Tractor Unit

MOT Due 30/11/2025

Cab Type LOW ROOF SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Air

HEAD GASKET GONE SLIDING 5TH WHEEL

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Radio/CD
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Qtr Panel Trim ns
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	Fault	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		